Work Orde											Page 1	
Item ID: Revision ID: Item Name:	D3706-3 Guide			1 14011161 WIN 18111 SEILL SEIL					etup Star			
Start Date: Required Date: Reference:	12/03/2010 26/03/2010	Start Qty: 10.00 Req'd Qty: 10.00		··	Cust Item I Customer:	D:				*	<b>                                   </b>	
Approvals:	Process Pla	n:	Date:/ <i>6-3-</i> Date:	Tooling: SPC (Y/N):		ite:		F	tun Star Sto	1 10011191 0		
Sequence ID/ Work Center ID	)	Operation Description		Set Up/ Run Hours	Draw Number	Draw Rev.	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp	
Draw Nbr	Revi	ision Nbr									<del></del> -	
D3706	Rev	A		1.0								
100  Doosan  Doosan Lathe		Memo Turn as per DWG REV	Dwg D3706 and Folio	0.00 0.00 FA833	10/03/2	2 (10	·				- <u> </u>	

0.00

0.00

DEBURR

Memo

QC2- Inspect parts off machine FAI/FAIB

Quality Control

## **Dart Aerospace Ltd**

W/O:			WC	RK ORDER CHANG	ES	-			
DATE	STEP	PR	NGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector	
-									
Part No		PAR #:							
	Res	olution:	Disposition	):	_ QA: N/C Cld	sed:		Date: _	·
NCR:			WORK ORDE	R NON-CONFORMA	ANCE (NCR	)			
DATE	STEP	Description of NC		on B Sign &	Verific	cation	Approval	Approval	
		Section A	Chief Eng	Initial Action Description Chief Eng Chief Eng		Secti	on C	Chief Eng	QC Inspector
						<u> </u>			
· · · · · · · · · · · · · · · · · · ·									

March 12, 2010 1:28:29 PM

**Required Date: 26/03/2010** 

Item ID:

D3706-3

Accept

Setup Start

Stop

**Revision ID:** 

Item Name: Guide

12/03/2010 **Start Qty: 10.00** 

Req'd Qty: 10.00



**Cust Item ID: Customer:** 

Reference:

**Start Date:** 

Approvals:

Process Plan:

Date:\_\_\_\_

Tooling:

Date:

Run Start



QC:

Date: \_\_\_\_\_

SPC (Y/N):

Date:

Rev.

Stop

Sequence ID/

Work Center ID

140

Quality Control

Operation **Description** 

QC8- Inspect parts - second check

Memo

Memo

Set Up/ **Run Hours** 

0.00

Draw Number

Draw Plan Code

Accept Qty

Reject Qty

Reject Insp. Stamp

Number

150

Packaging

Packaging

Identify as per dwg & Stock Location: 87

0.00

0.00

160

Quality Control

QC21- Final Inspection - Work Order Release

0.00

Memo

0.00

10 l03/24 H

Dart Aerospace
----------------

W/O:			WO	RK ORDER CHANG	FS						
DATE	STEP	PROCEDURE CHANGE				Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector	
			7								
		PAR #:	: Fault Category: NCR: Yes No DQ				lo <b>DQ</b> /	A: Date:			
	Res	olution:	Disposition	:	_ QA: N	I/C Clo	sed:		Date:		
NCR:			WORK ORDE	R NON-CONFORM	ANCE (	NCR)					
DATE	STEP	Description of NC	Corrective Action Section B				Verific	ation	Approval	Approval	
		Section A	Initial Chief Eng	Action Description Chief Eng		Sign & Date	Section C		Chief Eng	QC Inspector	
					·						

## **Picklist Print**

March 12, 2010 1:28:34 PM

Work Order ID: 56912

Parent Item:

D3706-3

Parent Item Name: **Comments:** 

Guide

IPP Rev:A New Issuie 08-06-04 JLM Verified By:EC

REV:B Now on Doosan JLM 10-01-13 Verified By:EC

IPP

**Start Date:** 12/03/2010

Required Date: 26/03/2010

**Start Qty: 10.00** 

Required Qty: 10.00

Component Item ID/ Item Name

Replacement Mfg/ Item ID Purch Purchased

Bin Primary Last Item Location Location No

Route Unit of Seq ID Measure 100

Qty on Hand 26.0270 4.5263

Remaining Qty Qty To Pick

Date Issued Issued

Status

Page 1

M6061T6R0.500



6061-T6 Round Bar .500"

Warehouse	Loc Qty	Loc Code
<b>Location</b>		

Main Warehouse

MAT 26.027 110532 24 111448 2.027

H16 JL 10/03/22

Dart Aerospace Lt
-------------------


	-											
W/O:		WORK ORDER CHANGES										
DATE	STEP	PROCEDURE CHANGE				Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector			
									,			
						· · · · · · · · · · · · · · · · · · ·						
					NCR: Yes No DQA: Date:							
Resolution:							···	Date:	<del></del>			
NCR:			WORK ORDI	R NON-CONFORM	IANCE (NC	R)	. 5000					
DATE	STEP	Description of NC	Corrective Action Section B Initial Action Description				cation	Approval	Approval			
	Section A		Initial Action Descri Chief Eng Chief Eng		otion Sign & Date		ion C	Chief Eng	QC Inspector			

DART AEROSPACE LTD	Work Order:	56917
Description: Guide	Part Number:	D3706-3
Inspection Dwg: D3706 Rev: A		Page 1 of 1

	FIRST ARTICLE INSPECTION CHECKLIST									
	X	First Arti	icle	Prot	otype		•			
Drawing Dimension	Tolerance	Actual Dimension	Accept	Reject	Method of Inspection	Co	mments			
Ø0.50	+/-0.030	. 498								
0.450	+/-0.010	.448	1							
3.38	+/-0.030	3.380			,					
0.03 x 45°	+/-0.030 x +/-0.5°	.025X45°	1/							
5.25	+/-0.030	5-249					442			
							······································			
							<del></del>			
						<del></del>				
				<del>_</del> ·		<del></del>				
		<u> </u>								
						.,				
							•			
							-			
							•			
Measured by:	الا	Audited by:	85		Prototype Ap	proval:	N/A			
Date:	10/03/2008	Date:	10/03/2	7		Date:	N/A			
Dov. Do4-			/ /	<u> </u>						
Rev         Date           A         09.05.15	Change  New Issue		·		Rev	rised by	Approved			
7. 109.00.10	J INCW ISSUE				KJ	944	1 INC			


Dart Aerospa	ıce	Ltd
--------------	-----	-----

	F	•							
W/O:			WC	RK ORDER CHANG	ES				
DATE	STEP	PROCEDURE CHANGE				Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
Part No	:	PAR #:	Fault Categ	jory:	NCR: Yes	No <b>DQ</b>	A:	Date:	
Resolution:									
NCR:			WORK ORDE	R NON-CONFORMA	NCE (NCF	R)			
DATE	STEP	Description of NC	Corrective Action Sect Initial Action Description		on B	Verification			Approval
<del> </del>		Section A	Chief Eng	Chief Eng	Date	Secti	on C	Chief Eng	QC Inspector
									-
								-	
	1 1		1		1	1			ŀ




## **Dart Aerospace Ltd**

1440	•									
W/O:			WC	RK ORDER CHANG	ES					
DATE	STEP	PRO	NGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector		
					NCR: Yes No DQA: Date:					
	Re	solution:						Date:		
NCR:			WORK ORD	ER NON-CONFORMA	ANCE (NCR)	)				
DATE	STEP	Description of NC	initial .	on B Sign &	Verific	ation	Approval	Approval		
		Section A	Chief Eng	Initial Action Description Chief Eng Chief Eng		Section C		Chief Eng	QC Inspector	




Dart Aerospa	ce Ltd
--------------	--------

	•								
W/O:			W	ORK ORDER CHANGE	ES				
DATE	STEP	PROCEDURE CHANGE			Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
			<del></del>						
			*****						
Part No	•	PAR #:	_ Fault Cat	egory:	NCR: Yes	No DQ	<b>A:</b>	Date: _	
Resolution: Disposition:									
NCR:		W	ORK ORI	DER NON-CONFORMA	NCE (NCF	?)			
DATE	STEP	Description of NC	Corrective Action Section B			Verific		cation Approval	Approvai
		Section A	Initial Chief Eng	Action Description Chief Eng	Sign 8 Date	Secti	on C	Chief Eng	QC Inspector
<del> </del>									-



	Dart	<b>Aeros</b>	pace	Ltd
--	------	--------------	------	-----

	•										
W/O:			W	ORK ORDER CHANG	GES		***		•		
DATE	STEP	PROCEDURE CHANGE			Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector		
Part No		PAR #:	Fault Cate	gory:	NCR: Yes	No DQ	A:	Date:			
	Resolution: Disposition:										
NCR:			WORK ORD	ER NON-CONFORM	ANCE (NCF	₹)					
DATE	STEP	Description of NC	Corrective Action Section B			Verifica		ation Approval	Approval		
		Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date		on C	Chief Eng	QC Inspector		
							:				



## **Dart Aerospace Ltd**

W/O:			W	JOK UDDED CHVIC	ES				······································	
DATE	STEP	WORK ORDER CHANGES  PROCEDURE CHANGE			Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector	
Part No		PAR #:	Fault Cate	gory:	_ NCR: Yes	No <b>DQ</b>	A:	Date:		
	Resolution: Disposition:									
NCR:			WORK ORD	ER NON-CONFORMA	ANCE (NCF	R)		***************************************	-	
DATE	STEP	Description of NC	Corrective Action Section B			Verifica		ation Approval	Approval	
	J	Section A	Initial Chief Eng	Action Description Chief Eng	Sign 8 Date	Secti	ion C	Chief Eng	QC Inspector	
									··	